
SR 0030/0462 Interchange Improvement Project

East Lampeter Township Board of Supervisors Meeting October 17, 2022













Purpose & Need

Purpose:

The purpose of the project is to provide safe vehicular movement and improved pedestrian mobility through the intersection of SR 30 and SR 462

Need:

The project is needed due to:

I. Significant crash history at the intersection of SR 0030, SR 0462, and Oakview Road

2. Lack of continuous sidewalk and pedestrian crossings





This project is consistent with East Lampeter Township's Lincoln Highway Streetscape Plan between Strasburg Pike and Harvest Road / Mennonite School Road







Improvements

Proposed improvements include:


- Realign SR 462 EB lanes to a new signalized intersection with SR 30 EB
- Reconfigure eastbound approach to SR 30 / Oakview Road intersection
- Complete sidewalk connections and pedestrian crossings through the project limits
- Reduce pavement width on SR 30 and SR 462
- Construct a 12' multi-use path between Oakview Road and Mennonite School Road
- Upgrade six traffic signal installations with decorative mast arms, pedestrian poles, and ADAcompliant curb ramps
- Additional fire hydrants on north side of SR 462 and SR 30







- Sidewalk connection to Volleyball Corner
- Extension of existing culvert under SR 0462
















- Pavement width reduction
- 6' sidewalk on both sides with large grass buffers
- 7' sidewalk on both sides underneath SR 30 overpass














Proposed Typical Section Looking East



APPROXIMATE WIDTH OF EXISTING PAVEMENT





- Realignment of EB lanes to signal at SR 30 EB
- All traffic turns left to single EB approach to Oakview Road
- Entrance to East Towne
 Centre is maintained














Proposed Typical Section Looking East






SR 30 / SR 462 / Oakview Road Intersection




- Single EB approach to Oakview Road
- Maintain textured crosswalks
- I2' multi-use trail on west side of Oakview Road with grass buffer





SR 30 / SR 462 / Oakview Road Intersection








SR 30 Improvements



- Pavement width reduction
- 6' sidewalk on north side with grass buffer
- I 2' multi-use trail on south side with grass buffer





SR 30 Improvements










SR 30 Improvements

Proposed Typical Section Looking East



APPROXIMATE WIDTH OF EXISTING PAVEMENT





Traffic Control During Construction

- Currently in development
- SR 30 and SR 462 traffic will be maintained in both directions with lane closures
- Short-term or weekend detours may be required on side streets





					P	roj	e	ct	Sc	he	edu	ule	<u>9</u>							
		20	22			20	23			20	24			20	25			20	26	
	1	2	3	4	1	2	3	4	1	2	3	4	1	2	3	4	1	2	3	4
PHASE 1	PREL	IMINA	RY DI	ESIGN																0
PHASE 2	1					FINAL	DESI	GN												0
PHASE 3	1				1				1				CONS	TRUCT	TION					





WE WANT TO HEAR FROM YOU

Fill out a comment form and give it to the project team or

Mail to:

Juli Wolfe, P.E., Senior Project Manager

c/o Michelle Scerbo

RETTEW

3020 Columbia Avenue

Lancaster, PA 17603

Email to:

juli.wolfe@rettew.com

Comments are vital to the success of the project and will be taken into consideration during design and construction.

	terchange Impro	
Please provide your name and cont	act information below:	
Name:		Date:
Address:		
City:	State:	Zip:
Phone Number:	Email:	
		oject:
	aking the time to provide us with ;	your comments.
	aking the time to provide us with y med in to the project team tonigh	your comments.





Thank You For Your Attention!

Any Questions?



For Additional Information Contact...

Juli Wolfe, P.E. Senior Project Manager 484-654-2003 | juli.wolfe@rettew.com